



Province of the
EASTERN CAPE
EDUCATION

**NATIONAL
SENIOR CERTIFICATE**

GRADE 11

NOVEMBER 2019

**MECHANICAL TECHNOLOGY:
WELDING AND METALWORK
MARKING GUIDELINE**

MARKS: 200

This marking guideline consists of 14 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

- 1.1 C ✓
- 1.2 B ✓
- 1.3 D ✓
- 1.4 C ✓
- 1.5 A ✓
- 1.6 B ✓
- 1.7 C ✓
- 1.8 A ✓
- 1.9 C ✓
- 1.10 B ✓
- 1.11 B ✓
- 1.12 D ✓
- 1.13 A ✓
- 1.14 A ✓
- 1.15 A ✓
- 1.16 B ✓
- 1.17 D ✓
- 1.18 C ✓
- 1.19 B ✓
- 1.20 B ✓

(20 x 1) [20]

QUESTION 2: SAFETY (GENERIC)**2.1 Gas welding (PPE)**

- Eye protection ✓
- Overall / leather apron ✓
- Safety boots ✓
- Gloves ✓

(Any 3 x 1) (3)

2.2 Hydraulic Press

- The predetermined pressure must not be exceeded ✓
- Pressure gauges must be tested regularly ✓
- The platform on which the work piece rests must be rigid and square ✓
- The platform must rest on the supporting pins ✓
- Place objects to be pressed in or out of the suitable jigs ✓
- Special tools and holding devices must be used to prevent damage to soft material ✓
- Ensure that the direction of pressure is always 90° to the platform. ✓
- Relieve pressure after use by opening the return valve ✓

(Any 3 x 1) (3)

2.3 **Surface Grinder**

- Do not force the work piece into the wheel ✓
 - Do not clean or adjust the machine while it is in motion ✓
 - Avoid large cuts ✓
 - Use coolant ✓
 - Know how to use the emergency stop ✓
 - Keep an eye on the position of the work piece ✓
 - Keep all tools clear of the work table ✓
 - Do not leave the machine while it is in operation ✓
 - Do not lean on the machine ✓
- (Any 3 x 1) (3)

2.4 Switch off the machine. ✓ (1)

2.5 **Bench Grinder**

- Make sure that there are no cracks or chips on the disc ✓
 - Make sure that the emery disc that is fitted is rated above the revolutions at which it is turned by the motor ✓
 - Make sure that the space between the tool rest and the emery disc does not exceed 3 mm ✓
 - Ensure that guards are in place ✓
 - When switching on the machine, do not stand in front of it until it reaches its full speed ✓
 - Do not force or bump the work piece against the emery disc ✓
 - Grind only on the front surface of the wheel not the sides ✓
 - All grinding machines must have a sign indicating the revolutions which the spindle rotates ✓
- (Any 3 x 1) (3)

2.6 To protect your eyes from flying sparks ✓ (1)

2.7 **Safety: Hand drill**

- Use a sharp drill of the right size for the type of material to be drilled. ✓
 - Remove the key from the chuck. ✓
 - Never leave the machine running unattended. ✓
 - Clamp the work piece securely on the vice or table. ✓
 - Never attempt to stop the machine with your hands if it slips. ✓
 - Do not force the drill on the work piece. ✓
 - Use a brush to remove chips from the drill. ✓
- (Any 3 x 1) (3)

2.8 Handling of gas bottles/cylinders

- Ensure the cylinders are stored in an upright position ✓
- The cylinders should be colour-coded ✓
- Full cylinders should be separated from empty ones ✓
- Keep away from direct sunlight ✓
- Keep protector cap on for protection ✓

(Any 3 x 1) (3)

2.9 Band saw

- Ensure there is no oil or grease around the machine ✓
- Ensure that all guides are in place before work commences ✓
- Ensure that the entire blade is guarded except at the point to cut ✓
- Ensure that the machine is switched off when changing blades or guides
- Wear eye protection ✓
- Ensure that the blade is fitted in the correct cutting direction ✓
- Round material must be clamped in a vice or holding device ✓
- Always use pusher against the work piece whenever possible ✓

(Any 3 x 1) (3)

2.10 Clamp the work piece in the vice or holding device ✓

(1)

[24]**QUESTION 3: TOOLS AND EQUIPMENT (GENERIC)****3.1 Function of tap and die set**

Tap is used to cut internal threads ✓ and die cuts external threads ✓

(2)

3.2 Purpose of extension bar of guillotine

Lengthens the work surface and supports longer material ✓✓

(2)

3.3 A Pressure gauge ✓

B Handle ✓

C Hydraulic press cylinder ✓

D Supporting pin ✓

E Adjustment holes ✓

F Plunger ✓

(6)

3.4 Functions of equipment

3.4.1 Angle grinder - is used for cutting, grinding and polishing ✓✓

(2)

3.4.2 Rolling machine – used to roll sheet metal ✓✓

(2)

3.4.3 Press machine – press fit or remove parts from each other ✓✓

(2)

[16]

QUESTION 4: MAINTENANCE (GENERIC)

4.1 Maintenance of pedestal grinder

Guards- always check that they are clamped ✓ before operation and have adequate clearance ✓ from the rotating grinding wheel (6 mm) (2)

4.2 Reducing friction when cutting holes

Apply cutting fluid ✓
Apply oil to the tip of drill bit ✓ (2)

4.3 Overloading is when the lubrication bearer of oil is squeezed out of the machine-bearing surfaces ✓✓ (2)

4.4 Lack of lubrication in a gear system

- Without lubrication friction between teeth contact surfaces becomes too great, resulting in loss of efficiency ✓
- Excessive noise ✓
- Overheating ✓
- Eventual mechanical failure ✓ (Any 2 x 1) (2)

[8]

QUESTION 5: MATERIALS (GENERIC)

5.1 Raw materials in the production of iron:

- Iron ore ✓
- Fuel (coke) ✓
- Fluxing agent (lime stone) ✓
- Air ✓ (Any 3 x 1) (3)

5.2 Blast furnace product

Pig Iron ✓ (1)

5.3 Electric-arc furnace

It is useful in the production of stainless steel, other high-alloy steels, ✓ or special steels requiring very close metallurgical control ✓ of grain or other structural qualities ✓ (3)

5.4 Functions of furnaces

5.4.1 Blast Furnace: It is used to convert iron ore to pig iron ✓✓ (2)

5.4.2 Bessemer converter furnace

It is used to convert molten pig iron to steel by the Bessemer process ✓✓ (2)

5.4.3 Open hearth furnace

It is used to convert scrap metal and other alloying elements into different kinds of steel ✓✓ (2)

5.5 5.5.1 Blast furnace ✓ (1)

- 5.5.2 A Small bell ✓
B Stack ✓
C Melting zone ✓
D Iron tap hole ✓
E Hot air supply hole from stove ✓
F Steel casing ✓
G Hopper / Load ✓ (7)

5.6 **Advantages of rotor plant**

- The molten metal is protected by a layer of slag ✓
- The oxidation of iron and other elements is minimised ✓
- The melting loss is lower than that of the cupola furnace ✓ (3)

5.7 **Properties of metals**

5.7.1 **Ductility** is the ability of a metal to change shape by stretching it along its length without breaking or drawing it into wire form ✓✓ (2)

5.7.2 **Brittleness** is the ability of a metal to break easily and fracture with little or no deformation ✓✓ (2)

5.7.3 **Plasticity** is the ability of a metal to change shape permanently. It is the reverse of elasticity ✓✓ (2)

5.7.4 **Toughness** is the ability of a metal to resist penetration, cracking, bending, breaking or stretching and remain intact after continual bending in opposite directions ✓ (2)

[32]

QUESTION 6: WELDING TERMINOLOGY (SPECIFIC)

6.1 Roof truss

It is a frame used to support a roof covering and to provide a structure which overhead cranes can be fixed ✓✓ (2)

6.2 Roof truss calculations

6.2.1 $Pitch = \frac{rise}{span}$

$$= \frac{3000}{12000} \checkmark$$

$$= \frac{1}{4} \text{ or (1 in 4) or 1 : 4 } \checkmark \quad (2)$$

6.2.2 $Slope = \frac{rise}{part\ of\ span\ over\ which\ rise\ takes\ place}$

$$= \frac{3000}{6000} \checkmark$$

$$= \frac{1}{2} \text{ or (1 in 2)}$$

$$= 1:2 \checkmark \quad (2)$$

6.2.3 Rafter length ($C^2 = A^2 + B^2$)

$$= 6^2 + 3^2 \checkmark$$

$$C = \sqrt{6^2 + 3^2}$$

$$C = 6,7 \text{ m } \checkmark \quad (2)$$

6.3 Advantages of using a template

- Cheap and easy to rectify mistakes ✓
- Ensures uniformity in production ✓
- Ensures accuracy and precision ✓
- Enables unskilled workers to use it relatively easy ✓ (Any 2 x 1) (2)

6.4 Definition of terms

6.4.1 Fusion zone is the portion of the weld where the parent metal has been fused ✓✓ (2)

6.4.2 Weld metal is part of the metal of a welded joint that has been melt during its formation ✓✓ (2)

6.5 Supplementary symbols

6.5.1 M – Machine ✓

6.5.2 G – Grind ✓ (2)

6.6 Methods of reducing distortion

- Skip welding method ✓
 - Alternate welding method ✓
 - Back step welding ✓
- (Any 2 x 1) (2)

[18]

QUESTION 7: TOOLS AND EQUIPMENT (SPECIFIC)

7.1 Purpose of oxy-acetylene regulators

- To indicate the pressure inside the cylinders ✓
- To reduce the cylinder pressure to working pressure ✓ (Any 1 x 1) (1)

7.2 Rolling machine used for bending thick plate

- Vertical roll ✓ (1)

7.3 Use of a guillotine

- To cut sheet metal ✓
- To cut plate metal ✓ (Any 1 x 1) (1)

7.4 Function of punching machine

- To cut steel profiles ✓
- To punch holes into steel plates ✓ (2)

7.5 Reasons why plasma cutter is preferred to oxy-acetylene

- High speed ✓
- Precision cutting ✓
- Low cost ✓
- Cuts thin and thick materials ✓
- Cuts smoothly ✓ (Any 2 x 1) (2)

[7]

QUESTION 8: FORCES (SPECIFIC)

8.1

8.1.1

8.1.2

FORCES	HORIZONTAL COMPONENTS	VERTICAL COMPONENTS
45 N	45 Cos 0 = 45N ✓	45 Sin 0 = 0
50 N	50Cos 90 = 0	50 Sin 90 = 50 N ✓
30 N	30Cos45 OR 30 Cos135 =	30 Sin 45 OR 30 Sin 135 =
	-21,21N ✓	21,21N ✓
TOTAL	23,79 N ✓	71,21 N ✓

(6)

8.2 **Take moments about RR**

$$LR \times 8 \text{ m} = (20 \times 6 \text{ m}) + (30 \times 4 \text{ m}) \checkmark$$

$$8LR = 120 + 120 \checkmark$$

$$LR = 30 \text{ N} \checkmark$$

Take moments about LR

$$RR \times 8 \text{ m} = (30 \times 4 \text{ m}) + (20 \times 2 \text{ m}) \checkmark$$

$$8RR = 120 + 40 \checkmark$$

$$RR = 20 \text{ N} \checkmark$$

(6)

8.3

$$\text{Stress} = \frac{\text{Force}}{\text{Area}}$$

$$\text{Area} = \frac{\pi (D^2 - d^2)}{4} \checkmark$$

$$= \frac{\pi(0,025^2 - 0,021^2)}{4} \checkmark$$

$$= 1,445133 \times 10^{-4} \text{ m}^2 \checkmark$$

$$\text{Stress} = \frac{10 \times 10^3}{1,445133 \times 10^{-4}} \checkmark$$

$$= 69197801,34 \text{ Pa}$$

$$= 69,2 \text{ MPa} \checkmark$$

(5)

[17]

QUESTION 9: MAINTENANCE (SPECIFIC)

9.1 Effects of overloading rolling machine

Limits the life span of components (bearings, gearbox, motor) ✓✓ (2)

9.2 Prevent excessive wear

The specified lubricant is to be applied to the relevant lubricating point in a specified quantity and at a specific time ✓ (1)

9.3 Lack of lubrication – Punch and shear machine


Components (moving parts) will cause excessive wear and result in the journals seizing in the bearings/bushes ✓✓ (2)

9.4 Friction not a relevant factor in machine

- Guillotine ✓
 - Punch ✓
- (Any 1 x 1) (1)
- [6]**

QUESTION 10: JOINING METHODS (SPECIFIC)

10.1



(5)

10.2 Purpose of normalising

To soften steel above its critical range and to cool it in still air ✓✓ (2)

10.3 MIGS – Metal inert gas shielded ✓

(1)

10.4 Undercutting

Causes

- Faulty electrode manipulation ✓
- Current too high ✓
- Arc length too long ✓
- Speed of weld too fast ✓
- Improper welding parameters ✓

(Any 1 x 1) (1)


Remedies

- Do not use too large electrodes ✓
- Use moderate current ✓
- Hold electrode at correct angle ✓

(Any 1 x 1) (1)


10.5 Welding joints

10.5.1



(2)

10.5.2



(2)

10.6 Inert gases for MIG/MAGS welding:


- CO₂ ✓
- Argon ✓
- Helium ✓
- Teral (Argon + CO₂) ✓

(Any 1 x 1) (1)

[15]

QUESTION 11: SYSTEMS AND CONTROLS (SPECIFIC)

11.1 Develop the square to round transition piece shown in FIGURE 11.1.



(9)
[19]

QUESTION 12: TERMINOLOGY (STEEL SECTIONS) (SPECIFIC)

12.1 **Steel bars**

12.1.1



(2)

12.1.2



(2)

12.2 **Purpose of an assembly jig**


To hold parts in position ✓ so that a number of identical items can be tack welded and easily removed before final welding is done ✓

(2)

12.3 **Channel iron**



(4)

12.4 **TWO preparation methods**

Methods of the ends of two equal angle iron bars that have to be welded at 90° to each other

(4)

12.5 **I- Beam** is a rolled steel joist (RS) that is used in heavier, structural steel construction ✓✓

(2)

12.6 **Disadvantage of welding steel section**

Components are permanently joined and sometimes difficult to transport due to size constrains ✓✓

(2)

[18]**TOTAL: 200**