



Province of the
EASTERN CAPE
EDUCATION



NATIONAL SENIOR CERTIFICATE

GRADE 12

SEPTEMBER 2022

MECHANICAL TECHNOLOGY: (WELDING AND METALWORK) MARKING GUIDELINE

MARKS: 200

This marking guideline consists of 11 pages.

SECTION A: COMPULSORY**QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)**

- 1.1 D ✓
1.2 B ✓
1.3 A ✓
1.4 C ✓
1.5 C ✓
1.6 B ✓

(6 x 1) [6]

QUESTION 2: SAFETY (GENERIC)**2.1 Personal protective equipment**

- Welding helmet ✓
- Leather apron ✓
- Leather hand gloves ✓
- Overall/work suit ✓
- Safety boot ✓

(Any 3 x 1) (3)

2.2 Arc welding safety precautions

- Wear correct PPE ✓
- The welding cables and electrode holder must be well insulated ✓
- Your eyes must be protected with a welding helmet before attempting any strike ✓
- Ensure there is no water in the environment ✓
- Keep combustible materials away from the welding area ✓

(Any 3 x 1) (3)

2.3 Reason why you must not force a drill bit into the workpiece

- It can cause a broken drill bit and possible injuries. ✓

(1)

2.4 Reason for clamping a small workpiece before drilling

- To avoid slipping ✓
- Prevent drill bit from breaking ✓
- To ensure smooth and straight drilling ✓

(Any 1 x 1) (1).

2.5 Safety precautions to be observed when handling gas cylinders

- Store or transport cylinders in an upright position ✓
- Avoid oil or grease from coming in contact with oxygen fittings ✓
- Never stack cylinders on top of one another ✓
- Do not bang or work on cylinders ✓
- Never allow cylinders to fall ✓

(Any 2 x 1) (2)

[10]

QUESTION 3: MATERIALS (GENERIC)

- 3.1 3.1.1 **Test required to determine the carbon content of a metal**
- Sound test ✓
 - Spark test ✓
- (Any 1 x 1) (1)
- 3.1.2 **Test required to determine the ductility of metal**
- Bending test ✓
- (1)
- 3.2 **Cutting colour coded metals from unmarked end**
- In order to keep its identity ✓
- (1)
- 3.3 **Types of case-hardening**
- Carburising ✓
 - Nitriding ✓
 - Cyaniding ✓
- (3)
- 3.4 **Effect of medium or high carbon steel on case-hardening**
- The hardness will penetrate the core of the steel ✓
- (1)
- 3.5 **Heat treatment process of metal**
- It has to do with heating metal to the required temperature, ✓ allow to soak in that temperature for a given period of time, ✓ then cool in the appropriate medium. ✓
- (3)
- 3.6 **Factors that determine the hardness of steel during heat treatment**
- Work size ✓
 - Quenching rate ✓
 - Carbon content ✓
- (3)
- 3.7 **Properties achieved from an annealed steel**
- Softness ✓
 - Ductility ✓
- (Any 1 x 1) (1)
- [14]**

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

- 4.1 B ✓
- 4.2 B ✓
- 4.3 C ✓
- 4.4 D ✓
- 4.5 A ✓
- 4.6 C ✓
- 4.7 D ✓
- 4.8 D ✓
- 4.9 A ✓
- 4.10 C ✓
- 4.11 C ✓
- 4.12 D ✓
- 4.13 D ✓
- 4.14 B ✓
- (14 x 1) **[14]**


QUESTION 5: TERMINOLOGY (TEMPLATES) (SPECIFIC)

5.1 Tools required in the template loft:

- Circular saw ✓
- Planer ✓
- Drilling machine ✓
- Steel tape
- Straight edge

(Any 3 x 1) (3)


5.2 Roof truss sketch:



✓✓✓✓✓

(5)

5.3 Rectangular lattice girder sketch:



✓✓✓✓

(4)

5.4 Calculations of a basketball ring:

Mean Θ = Outside Θ – plate thickness ✓

OR

Inside Θ + plate thickness

Mean Θ = 320 – 30 ✓

= 290 mm ✓

Mean Circumference = $\pi \times$ mean Θ

= $\pi \times 290$ ✓


= 911,18 ✓

Rounded of to 911 for one ring. ✓

911 x 2 = 1 822 mm for the set of two rings. ✓

(7)

5.5 T-joint sketch:



(4)

[23]

QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)**6.1 Consequences of aluminum on a grinding wheel:**

The soft material lodges in the pores of the wheel and expands. ✓

Pieces can dislodge when the wheel is revolving at a high-speed causing injury. ✓

(2)

6.2 Function of the following:**6.2.1 Angle grinder: ✓**

To cut, grind or polish material. ✓

(2)

6.2.2 Guillotine:

To cut ✓ sheet metal. ✓

(2)

6.3 Types of press machines:

Manual press machine. ✓

Hydraulic press machine. ✓

(2)

6.4 Principles of arc welding equipment (inverters):

- Inverters use electronic circuits ✓ to convert AC to DC ✓ by inverting the sine wave signal. ✓

- The steady arc that is produced by the DC power source ✓ ensures a neater weld bead with less spatter. ✓

(5)

6.5 Types of rolling machines:

A – Pyramid rolls ✓

B – Off-set pinch rolls ✓

C – Vertical rolls ✓

(3)

6.6 Purpose of plasma cutter:

Plasma cutting is a process that cuts through electrically conductive materials ✓ by means of an accelerated jet of hot plasma e.g., steel, aluminium, brass and copper. ✓

(2)

[18]

QUESTION 7: FORCES (SPECIFIC)**7.1 STRESS AND STRAIN****7.1.1 Stress**

$$\text{Area} = \frac{\pi d^2}{4} \quad \checkmark \checkmark$$

$$= \frac{\pi \times (0,024)^2}{4} \quad \checkmark$$

$$= 4,525 \times 10^{-4} \text{ m}^2 \quad \checkmark$$

$$\text{Stress} = \frac{\text{Force}}{\text{Area}}$$

$$= \frac{60 \times 10^3}{4,525 \times 10^{-4}} \quad \checkmark$$

$$= 132,579 \times 10^6 \text{ Pa}$$

$$= 132,58 \text{ MPa}$$

(6)

7.1.2 Strain

$$\text{Strain} = \frac{\text{Change in length}}{\text{Original length}} \quad \checkmark \checkmark$$

$$= \frac{0,22 \times 10^{-3}}{212 \times 10^{-3}} \quad \checkmark$$

$$= 1,038 \times 10^{-3}$$

$$= 1,04 \times 10^{-3} \quad \checkmark$$

(4)

7.1.3 Young's modulus

$$\text{Young's modulus of Elasticity (E)} = \frac{\text{Stress}}{\text{Strain}} \quad \checkmark \checkmark$$

$$= \frac{132,58 \times 10^6}{1,04 \times 10^{-3}} \quad \checkmark$$

$$= 127,48 \times 10^9 \quad \checkmark$$

$$= 127,48 \text{ GPa} \quad \checkmark$$

(6)

7.1.4 Youngs' modulus on softer materials will decrease $\checkmark \checkmark$
or be lower than harder materials. $\checkmark \checkmark$

(4)

7.2 Reactions

Take reactions **A** and **B**

$$\mathbf{A} \times 6 = (600 \times 4) + (400 \times 3) + (500 \times 2) \quad \checkmark$$

$$= 2\,400 + 1\,200 + 1\,000$$

$$= 4\,600/6 \quad \checkmark$$

$$\mathbf{A} = 766,67 \text{ N} \quad \checkmark$$

$$\mathbf{B} \times 6 = (500 \times 4) + (400 \times 3) + (600 \times 2) \quad \checkmark$$

$$= 2\,000 + 1\,200 + 1\,200$$

$$= 4\,400/6 \quad \checkmark$$

$$\mathbf{B} = 733,33 \text{ N} \quad \checkmark$$

(6)

7.3 7.3.1 **STRAIN**

Strain = $\frac{\text{Change in length}}{\text{Original length}}$ ✓

Strain = $\frac{14,4 \times 10^{-3}}{80}$ ✓

= $1,8 \times 10^{-4}$ ✓ (3)


7.3.2 **Young's modulus:**

E = $\frac{\text{Stress}}{\text{Strain}}$ ✓

E = $\frac{16 \times 10^6}{1,8 \times 10^{-4}}$ ✓

= 88,9 GPa ✓ (3)

7.4 7.4.1 **Sketch of shearing stress**



✓✓✓ (3)

7.4.2 **Sketch of tensile stress**



✓✓✓ (3)

7.5 **Purpose of tensile test:**

It is used to determine ✓ the tensile strength of material. ✓ (2)

7.6 7.6.1 **Hooke's law:**

Strain is directly proportional ✓ to the stress its deformation causes, ✓ provided the limit of proportionality is not exceeded. ✓ (3)

7.6.2 **Safety factor:**

It is the maximum number of times ✓ with which the maximum stress is decreased, to obtain a safe stress. ✓ (2)

[45]

QUESTION 8: JOINING METHODS (INSPECTION OF WELDS) (SPECIFIC)**8.1 Welding processes for inspection:**

- Is there fusion between the weld metal and the parent metal? ✓
- Is there an indentation, denoting undercutting along the line where the weld joins the parent metal (lines of fusion)? ✓
- Has penetration been obtained right through the joint, indicated by the weld metal appearing through the bottom of the V or U on a single V or U-joint? ✓
- Has the joint been built up on its upper side or has the weld a concave side on its face, denoting lack of metal and thus weakness? ✓ (4)

8.2 Uses of weld gauges:


- To check the angle of preparation. ✓
- To check the misalignment. ✓
- To check the fillet leg/excess weld metal. ✓
- To check the fillet throat.
- To check for undercutting. (Any 3 x 1) (3)

8.3 Incomplete penetration:

- When the weld bead does not penetrate the full depth of the weld or into the root of the weld. ✓
- When two opposing weld beads do not inter-penetrate. ✓
- When the weld bead does not penetrate to the toe of a fillet weld, but only bridges across it. ✓ (3)

8.4 'Presence of pits':

Porosity ✓ (1)

8.5 Sketch of undercutting:

✓✓

(2)

8.6 Welding spatter:

It is little droplets of molten material, ✓ that are generated at or near the welding arc. ✓ (2)

8.7 Three welding flames:

- Neutral flame ✓
- Carburising flame ✓
- Oxidising flame ✓ (3 x 1) (3)

8.8 Types of cracks:

- Heat affected zone (HAZ) ✓
- Centre line cracks ✓
- Crater cracks ✓
- Transverse cracks (Any 3 x 1) (3)

8.9 Types of destructive tests:

- Nick break test ✓
- Guided bend test ✓
- Free-bend test
- Machinability test (Any 2 x 1) (2)

[23]**QUESTION 9: JOINING METHODS (STRESSES AND DISTORTION) (SPECIFIC)****9.1 Weld distortion:**

Weld distortion is the warping of the base metal ✓ caused by the heat from the welding arc/flame. ✓ (2)

9.2 Methods to reduce distortion:

- Do not overweld. ✓
- Apply intermittent welding. ✓
- Place welds near the neutral axis. ✓
- Use as few passes as possible.
- Use back-step welding.
- Anticipate the shrinking forces.
- Plan the welding sequence.
- Use strong backs. (Any 3 x 1) (3)

9.3 Difference between hot working and cold working:

Hot working is when deformation of steel ✓ takes place above the recrystallisation temperature of the steel. ✓
Cold working is when deformation of steel ✓ takes place below the recrystallisation temperature of the steel. ✓ (4)

9.4 Effect of electrode size:

The larger the welding electrode diameter, ✓ the higher the current ✓ that is required to weld and therefore the higher the welding temperature. ✓ (3)

9.5 Factors for setting up residual stress:

- Heat present in the weld. ✓
- Qualities of parent metal, filler rod or electrode. ✓
- Shape and size of weld. ✓
- Number of successive welds runs.
- Comparative weight of weld metal and parent metal.
- Type of welding joint. (Any 3 x 1) (3)

9.6 Examples of distortion:

- Pre-bending. ✓
- Pre-setting the parts to be welded. ✓
- Pre-springing the parts to be welded. ✓ (3)

[18]


QUESTION 10: MAINTENANCE (SPECIFIC)**10.1 Responsibility of employer-maintenance:**

Employer should think about the hazards which can occur if:

- The tools break during use. ✓
 - Machines starts up unexpectedly. ✓
 - Contact is made with materials that are normally enclosed within the machine.
- (Any 2 x 1) (2)

10.2 Possible causes of malfunction:

- Lack of lubrication or incorrect lubrication. ✓
 - Overloading ✓
 - Friction
- (Any 2 x 1) (2)

10.3 Labels on punching and shearing machine:

✓✓✓✓

(4)
[8]

QUESTION 11: TERMINOLOGY (DEVELOPMENT)

11.1 11.1.1 Vertical height CE:

$$\text{In triangle CED: } \tan \Theta = \frac{\text{Opposite (CE)}}{\text{Adjacent (ED)}} \checkmark$$

$$\text{CE} = \tan 75^\circ \times \text{ED} \text{ (205)} \checkmark$$

$$= 765,07 \text{ mm} \checkmark \quad (3)$$

11.1.2 Main radius AD: $\cos \Theta = \frac{\text{Adjacent (BD)}}{\text{Hypotoneuse (AD)}} \checkmark$

$$\text{AD} = \frac{450}{\cos 75^\circ} \checkmark$$

$$= 1\,738,67 \text{ mm} \checkmark \quad (3)$$

11.1.3 Small radius AC:

$$\text{In triangle CED: } \cos 75^\circ = \frac{\text{Adjacent (205)}}{\text{Hypotoneuse (CD)}} \checkmark$$

$$\text{CD} = \frac{205}{\cos 75^\circ} \checkmark$$

$$= 792,06 \text{ mm} \checkmark$$

$$\text{BUT, } \text{AC} = \text{AD} - \text{CD}$$

$$= 1\,738,67 - 792,069 \checkmark$$

$$= 946,601 \text{ mm} \checkmark \quad (5)$$

11.1.4 Circumference = $\pi \times \text{Diameter}$

$$= \pi \times 900 \checkmark$$

$$= 2\,827,8 \text{ mm} \checkmark \quad (2)$$

11.2 11.2.1 $CD^2 = \sqrt{60^2 + 120^2} \checkmark$

$$= \sqrt{18\,000}$$

$$\text{CD} = 134,16 \checkmark \quad (2)$$

11.2.2 $AD^2 = \sqrt{60^2 + 60^2 + 120^2} \checkmark$

$$= 21\,600 \checkmark$$

$$\text{AD} = 146,97 \checkmark \quad (3)$$

11.2.3 $DB^2 = \sqrt{60^2 + 240^2 + 120^2} \checkmark$

$$= 75\,600 \checkmark$$

$$\text{DB} = 274,95 \checkmark \quad (3)$$

[21]**TOTAL: 200**