

# higher education & training

Department:
Higher Education and Training
REPUBLIC OF SOUTH AFRICA

### MARKING GUIDELINE

## NATIONAL CERTIFICATE BUILDING ADMINISTRATION N5

17 August 2021

This marking guideline consists of 5 pages.

Copyright reserved Please turn over

#### -2-BUILDING ADMINISTRATION N5

#### **QUESTION 1**

1	.1	B
4	_	

1.2 C

1.3 A

1.4 D

1.5 C

1.7 B

1.6

1.8 C

1.9 C

#### **QUESTION 2**

2.1 False

2.2 False

2.3 True

2.4 False

2.5 False

 $(5 \times 1)$  [5]

 $(10 \times 1)$ 

[10]

#### **QUESTION 3**

- The machine must be able to carry out its task economically.
  - There must be sufficient work to keep the machine occupied.
  - There must be sufficient labour and allied services available.

The ability of the haul unit to position under the excavator bucket

Maximum hourly output is possible


Regular inspection by a competent mechanic to ensure that the machines are in good order

[6]

#### **QUESTION 4**

- 4.1 Preliminary negotiations
  - Labour requirements and site organisation
  - Preparation of contract programme
  - Site layout and ancillary arrangements
  - Setting up a reviewing system (5)

Copyright reserved Please turn over



#### **QUESTION 6**

- Check correctness of buyer's order copy
  - Check correctness of deliveries
  - Supply material from store room internally
  - Keep stock register
  - Update material delivery board
  - Follow proper storage methods

 $(Any 4 \times 1)$  (4)

- Small and expensive items must be issued by the storekeeper and a record should be kept.
  - Accurate stock control must be maintained with regular checks.
  - The compound must be fenced.
  - Storage areas should be locked.
  - Cars should be kept away from the construction area.
  - Delivery vehicles should be inspected when leaving.
  - Storage areas should be well lit.

 $(Any 4 \times 1)$  (4)

Copyright reserved Please turn over